

Under Review Notification

Raised By: Victoria Seib
 Date: 19.07.05

Product #: D350-591
 Product Name: Heli-Access Step

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D5496-1	D5496 Rev. C	Y	N	N	Y	Y	N	N	19-804	Update Drawing

Description of Issue:
 Paint on the D5496-1 is causing interference when installed with the D5491-041/-042 Step. Prime and Paint will be revised to black anodise.
Only product affected is D350-591-411/-412

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene